

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number H40007246049		2. Page 1 of 1		3. Emergency Response Phone (800) 483-3719		4. Manifest Tracking Number <b>008037566 FLE</b>				
		5. Generator's Name and Mailing Address Clean Harbors Kansas LLC 2543 North New York Street Wichita, KS 67219 Generator's Phone: (316) 289-7400						Generator's Site Address (if different than mailing address) SAME				
6. Transporter 1 Company Name U.S. Bulk Transportation Inc		U.S. EPA ID Number PA8987347515										
7. Transporter 2 Company Name		U.S. EPA ID Number										
8. Designated Facility Name and Site Address Clean Harbors Lone Mountain LLC 40365 S County Road 236 Wichita, KS 67202 Facility's Phone: (316) 607-3500		U.S. EPA ID Number ORD065438376										
GENERATOR	9a. HM	9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))				10. Containers		11. Total Quantity	12. Unit Wt./Vol.	13. Waste Codes		
						No.	Type					
	1.	HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG II				1	DT	EST 16	Y	F001	F002	F003
	2.									F004	F005	
	3.											
	4.											
14. Special Handling Instructions and Additional Information J. CHS11504X08 ERG#171 TR# 347-3 TL# 7/08												
15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.												
Generator's/Offor's Printed/Typed Name Jim Tyson												
Signature Jim Tyson												
Month Day Year 2 5 15												
TRANSPORTER	16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S. Port of entry/exit: Date leaving U.S.:											
	Transporter signature (for exports only):											
	17. Transporter Acknowledgment of Receipt of Materials											
Transporter 1 Printed/Typed Name MARK CARTER												
Signature Mark Carter												
Month Day Year 2 5 15												
Transporter 2 Printed/Typed Name												
Signature												
Month Day Year												
DESIGNATED FACILITY	18. Discrepancy											
	18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection											
	Manifest Reference Number:											
	18b. Alternate Facility (or Generator) U.S. EPA ID Number											
	Facility's Phone:											
18c. Signature of Alternate Facility (or Generator)												
Month Day Year												
19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)												
1. H132		2.		3.		4.						
20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a												
Printed/Typed Name												
Signature												
Month Day Year												

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

<b>UNIFORM HAZARDOUS WASTE MANIFEST</b>		1. Generator ID Number <b>KS0007245846</b>		2. Page 1 of <b>1</b>		3. Emergency Response Phone <b>(800) 483-3718</b>		4. Manifest Tracking Number <b>008037566 FLE</b>											
		5. Generator's Name and Mailing Address <b>Clean Harbors Kansas LLC 2548 North New York Street Wichita, KS 67219</b> Generator's Phone: <b>(316) 269-7400</b>						Generator's Site Address (if different than mailing address) <b>SAME</b>											
<b>GENERATOR</b>		6. Transporter 1 Company Name <b>U.S. Bulk Transportation Inc</b>						U.S. EPA ID Number <b>PA0987347515</b>											
		7. Transporter 2 Company Name						U.S. EPA ID Number											
<b>DESIGNATED FACILITY</b>		8. Designated Facility Name and Site Address <b>Clean Harbors Lone Mountain LLC 40355 S County Road 236 Wichita, KS 67220</b> Facility's Phone: <b>(316) 697-3800</b>						U.S. EPA ID Number <b>OKD065438376</b>											
		9a. HM						9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, and Packing Group (if any))		10. Containers									
<b>GENERATOR</b>				10. Containers		11. Total Quantity		12. Unit Wt./Vol.		13. Waste Codes									
				No.		Type													
		1. <b>HA3077, HAZARDOUS WASTE, SOLID, N.O.S., (F001, F003), 9, PG III</b>		<b>1</b>		<b>DT</b>		<b>EST 16</b>		<b>Y</b>		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td>F001</td> <td>F002</td> <td>F003</td> </tr> <tr> <td>F004</td> <td>F005</td> <td></td> </tr> </table>		F001	F002	F003	F004	F005	
		F001	F002	F003															
		F004	F005																
2.																			
3.																			
<b>GENERATOR</b>		4.																	
<b>DESIGNATED FACILITY</b>		14. Special Handling Instructions and Additional Information <b>1. CH831502X08</b> <b>ERG#171</b>  <b>TR# 347-3</b> <b>TL# 7108</b>																	
		15. <b>GENERATOR'S/OFFEROR'S CERTIFICATION:</b> I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.																	
<b>TRANSPORTER</b>		Generator's/Officer's Printed/Typed Name <b>Jim Tyson</b>						Signature <i>Jim Tyson</i>		Month   Day   Year <b>2 5 15</b>									
		16. International Shipments <input type="checkbox"/> Import to U.S. <input type="checkbox"/> Export from U.S.						Port of entry/exit: Date leaving U.S.:											
<b>TRANSPORTER</b>		17. Transporter Acknowledgment of Receipt of Materials																	
		Transporter 1 Printed/Typed Name <b>MARK CARTER</b>						Signature <i>Mark Carter</i>		Month   Day   Year <b>2 5 15</b>									
<b>TRANSPORTER</b>		Transporter 2 Printed/Typed Name						Signature		Month   Day   Year									
<b>DESIGNATED FACILITY</b>		18. Discrepancy																	
		18a. Discrepancy Indication Space <input type="checkbox"/> Quantity <input type="checkbox"/> Type <input type="checkbox"/> Residue <input type="checkbox"/> Partial Rejection <input type="checkbox"/> Full Rejection  Manifest Reference Number:      U.S. EPA ID Number																	
<b>DESIGNATED FACILITY</b>		18b. Alternate Facility (or Generator)																	
		Facility's Phone:      U.S. EPA ID Number																	
<b>DESIGNATED FACILITY</b>		18c. Signature of Alternate Facility (or Generator)																	
		Month   Day   Year																	
<b>DESIGNATED FACILITY</b>		19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems)																	
		1. <b>H132</b> 2.      3.      4.																	
<b>DESIGNATED FACILITY</b>		20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a																	
		Printed/Typed Name <b>Rutha Sparkman</b>						Signature <i>Rutha Sparkman</i>		Month   Day   Year <b>02 06 15</b>									